




26247

AO

-34

I 3/4

e = 0.20

26244

AO

-34

I 3/4

e = 0.20

26245

AP

-41

AO

-34

I 3/4

e = 0.20

26246

AO

-34

I 3/4

e = 0.20

26243

AO

-34

I 3/4

e = 0.20

26240

AO

-34

II

e = 0.20

26241

AO

-34

I 3/4

e = 0.20

26242

AO

-34

I 3/4

e = 0.20

AP-47